Olallie Scenic Area Campgrounds and Recreation Sites 2012 Prospectus

Appendix 3 - Government Furnished Property

FACILITY	number of sites (single/double/si ngle-walk in/group)	tables (good/fair/poor)	fire rings (good/fair/poor)	unit markers in place	barrier posts (have/need)	parking pad	vault toilets	recreation entrance sign	entrance gate	fee station board/ bulletin board	notes
O F O							1 Romtec good & 1 stick	being			
Camp Ten Campground	10/0/0/0	9/1/0	9/0/1	9 of 10	29 / 10	10 native	frame fair	painted	n	double	
Horseshoe Lake Campground	8/1/1/0	10/4/0	6/0/4	8 of 10	9/38	10 native	Romtec good	being painted	n	4'x4' fair	4 sites have two tables
Lower Lake Campground	8	9/0/0	8/0/0	8 of 9	33/17	9 native	CXT good	being painted	n	double	
Olallie Guard Station Cabin	n/a		0	0	0	20 native	shared Romtec with Picnic Area	n	n	n/a	*
Olallie Lake Picnic Area	5 day sites	5				gravel group	Romtec good	being painted	n		primitive boat ramp
Olallie Meadow Cabin	n/a	1 fair	1 good	0	0/5	native	uses campground toilet	being painted	n	n/a	**
Olallie Meadow Campground	7/0/0/0	3/3/1	2/5/0	5 of 7	10/0	7 native	CXT good				Olallie Meadow cabin in CG
Paul Dennis Campground	16/0/0/0	16/0/0	16/0/0	16 of 16	11/19	16 native	2 Romtecs fair & 2 stick built poor	У		two 4x4' (one fair one poor)	1 stick built toilet screwed shut and needs decomissioning
Peninsula Campground	30/1/5/1	30/20/10	30/28/2	30/30		30 native	1 CXT & 5 Romtecx - good	being painted	n	two 4x4' fair	amphitheater & group site & boat ramp
Triangle Lake Equestrian Campground	8/0/0/0	9/0/0	6/1/1	8 of 8	0/29	8 gravel	rustic prefab - fair	being painted	n	two (one 5x3' & one 3 panel kiosk) fair	horse ramp 8.5'x24' good each site has horse corral in good condition

^{*}Guard Station has a wood stove, 2 full size futons beds/couches, full bed in loft area, propane oven, bunk bed, table, kitchen equipment (plates, cups, pans, for 8) plus storage building (approx

**Olallie Meadow Cabin still has some repairs prior to being operational. Furniture is scheduled to be purchased. Floor and

Condition Ratings: Fair (need repair or maintenance) and Poor (need replacement)

Parking pad sizes on separate page